

Message

From: Myers, Hugh [hugh.myers@doh.hawaii.gov]
Sent: 2/10/2021 6:23:26 PM
To: Linder, Steven [Linder.Steven@epa.gov]
Subject: Re: Is this location near the new release you are investigating related to Red Hill distribution piping?
Attachments: Hotel Pier leak locations.pdf

Yes, it is very close. Is there any information on this release point? Pass release in 2019? Was it fixed? What was being released?

Attached is potential release point. Navy has contracted a company to relieve the regular harbor folks from dealing with the release and clean up.

They should be under contract hopefully by next week. USCG is involved as well now. Fresh JP-5 product fuel was discovered in electrical utility manhole by Valve station 3 last week Thursday.

FLC is trying to determine if the electrical utility manhole is CP or pass through for their cabling for the automated portion of the valve control system.

January pipeline pressure tests results expected in a couple weeks.

Roxanne asked me to go down tomorrow with HEER team on their weekly visit.

vr,
Hugh

From: Linder, Steven <Linder.Steven@epa.gov>
Sent: Wednesday, February 10, 2021 6:44 AM
To: Myers, Hugh <hugh.myers@doh.hawaii.gov>
Subject: [EXTERNAL] Is this location near the new release you are investigating related to Red Hill distribution piping?

Public Viewer

Map Layers | Geometry Points

Identity: Total 1 record(s) found

Attribute	Value
Category: REPORT INFORMATION	
REPORT_NUMBER	20190227
YEAR	2019
CPID	26046
NAME	PAR HAWAII REFINING, LLC
LOCAL_DATETIME	9/28/2019
NRC REPORT	1251354
COMMODITY_RELEASED	REFINED AND/OR PETROLEUM PR...
LOSS_BBLs	0.10
RECOVERED_BBLs	0.10
FATAL	0
INJURE	0
ON_OFF_SHORE	ONSHORE
CAUSE	CORROSION

Steven Linder, P.E.
Red Hill and NERT Project Coordinator (LND-4)
US Environmental Protection Agency Region 9
San Francisco, California
Linder.Steven@epa.gov
415-972-3369 – office
650-592-2000 - mobile